


# Pneumatic counter

## Counter

**Temperature range:**  
-10°C to + 60°C

**Function**

Arriving signals are added. On resetting (only using the key) the figure 000000 appears.



| Article number | Work pressure | Height (H) | Thread | Weight |
|----------------|---------------|------------|--------|--------|
| <b>PTM5</b>    | 5/2           | 4 mm       | M5     | 95 g   |